

# City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form

Page 1 of 4

Sewershed : Gwynn Falls

Company : URS

Date : 10/10/2008

Test to be Performed :  
Smoke : X Dyed Water :   

Ground Condition :  
Dry : X Damp :    Wet :   


Supervisor : John Daly

Manhole ID : S05MM1013MH

Test ID : S1032-034031

Notifications (Residents, Fire, 311) :  
Yes

**Field Sketch :** (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)



# City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form

Page 2 of 4

Sewershed : Gwynn Falls

Company : URS

Date : 10/10/2008

Test to be Performed :  
Smoke : X Dyed Water :   

Ground Condition :  
Dry : X Damp :    Wet :   

Supervisor : John Daly


Manhole ID : S05MM1013MH

Test ID : S1032-034031

Notifications (Residents, Fire, 311) :  
Yes

**Field Sketch :** (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)

ID



Location: N/A; Type: Service Lateral; Smoke: Medium; Status: Public ROW

Landscape



Defect



ID



Location: N/A; Type: Storm Manhole; Smoke: Heavy; Status: Public ROW

Landscape



Defect





# City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form

Page 3 of 4

Sewershed : Gwynn Falls

Company : URS

Date : 10/10/2008

Test to be Performed :  
Smoke : X Dyed Water :   

Ground Condition :  
Dry : X Damp :    Wet :   

Supervisor : John Daly


Manhole ID : S05MM1013MH

Test ID : S1032-034031

Notifications (Residents, Fire, 311) :  
Yes

**Field Sketch :** (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)

ID



Location: N/A; Type: Service Lateral; Smoke: Light; Status: Public ROW


Landscape



Defect



ID



Location: N/A; Type: Service Lateral; Smoke: Medium; Status: Public ROW

Landscape



Defect



# City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form

Page 4 of 4

Sewershed : Gwynn Falls

Company : URS

Date : 10/10/2008

Test to be Performed :  
Smoke : X Dyed Water :   

Ground Condition :  
Dry : X Damp :    Wet :   

Supervisor : John Daly


Manhole ID : S05MM1013MH

Test ID : S1032-034031

Notifications (Residents, Fire, 311) :  
Yes

**Field Sketch :** (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)

ID



Location: N/A; Type: Downspout Connection;  
Smoke: Heavy; Status: Private Property


Landscape



Defect



ID



Location: N/A; Type: Foundation Drain; Smoke:  
Heavy; Status: Private Property

Landscape



Defect

